

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	29-JUN-24	B	S02	12	5022	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	1	5061	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	2	5062	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	3	5063	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	4	5064	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	5	5065	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	6	5066	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	7	5067	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	8	5068	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	9	5069	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	10	5070	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S02	11	5071	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	4	G083
<b>Machine Total:</b>								<b>11</b>	<b>91</b>		
	29-JUN-24	B	S04	13	5033	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	2	G083
		B	S04	1	5073	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	2	5074	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	3	5075	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	4	5076	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	5	5077	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	6	5078	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	7	5079	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	8	5080	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	9	5081	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	10	5082	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	11	5083	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
B	S04	12	5084	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	1	G083		
<b>Machine Total:</b>								<b>12</b>	<b>91</b>		
	29-JUN-24	B	S06	12	5046	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	6	G083
		B	S06	1	5085	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	2	5086	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	3	5087	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	4	5088	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	5	5089	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	6	5090	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	7	5091	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	8	5092	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	9	5093	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	10	5094	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	11	5095	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	5	G083
<b>Machine Total:</b>								<b>11</b>	<b>91</b>		
	29-JUN-24	B	S07	1	5098	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	2	5099	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	3	5100	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	4	5101	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY		
S	29-JUN-24	B	S07	5	5102	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	6	G083		
		B	S07	6	5103	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	7	5104	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	8	5105	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	9	5106	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	10	5107	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	11	5108	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	12	5109	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		B	S07	13	8110	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
		<b>Machine Total:</b>								<b>13</b>	<b>90</b>		
			29-JUN-24	B	S08	13	5058	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	1	G083
				B	S08	1	5212	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
				B	S08	2	5213	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
B	S08			3	5214	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083		
B	S08			4	5215	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			5	5216	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			6	5217	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			7	5218	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			8	5219	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			9	5220	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			10	5221	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08			11	5222	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083		
B	S08	12	5223	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083				
<b>Machine Total:</b>								<b>12.5</b>	<b>88</b>				
<b>Shift Total:</b>								<b>59.5</b>	<b>451</b>				
<b>Day Total:</b>								<b>59.5</b>	<b>451</b>				
<b>Type Total:</b>								<b>59.5</b>	<b>451</b>				
<b>Grand Total:</b>								<b>59.5</b>	<b>451</b>				