

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	29-JUN-24	A	S02	13	4921	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	2	G083
		A	S02	1	5011	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	2	5012	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	3	5013	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	4	5014	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	5	5015	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	6	5016	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	7	5017	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	8	5018	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	9	5019	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	10	5020	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	11	5021	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S02	12	5022	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	1	G083
			<b>Machine Total:</b>					<b>12</b>		<b>91</b>	
	29-JUN-24	A	S04	12	4972	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	5	G083
		A	S04	1	5023	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	2	5024	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	3	5025	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	4	5026	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	5	5027	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	6	5028	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	7	5029	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	8	5030	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	9	5031	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	10	5032	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S04	11	5033	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	6	G083
			<b>Machine Total:</b>					<b>11</b>		<b>91</b>	
	29-JUN-24	A	S06	13	4983	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	1	G083
		A	S06	1	5035	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	2	5036	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	3	5037	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	4	5038	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	5	5039	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	6	5040	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	7	5041	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	8	5042	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	9	5043	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	10	5044	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	11	5045	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S06	12	5046	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	2	G083
			<b>Machine Total:</b>					<b>12</b>		<b>91</b>	
	29-JUN-24	A	S08	1	5047	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		A	S08	2	5048	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		A	S08	3	5049	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083

MURLIDHAR RATANLAL EXPORTS LIMITED  
 UNIT: HASTINGS JUTE MILL

Print Date : 29-JUN-24 05:19 PM

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	29-JUN-24	A	S08	4	5050	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		A	S08	5	5051	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S08	6	5052	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S08	7	5053	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S08	8	5054	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S08	9	5055	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		A	S08	10	5056	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		A	S08	11	5057	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		A	S08	12	5058	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	6	G083
<b>Machine Total:</b>								<b>11.5</b>		<b>88</b>	
<b>Shift Total:</b>								<b>46.5</b>		<b>361</b>	
<b>Day Total:</b>								<b>46.5</b>		<b>361</b>	
<b>Type Total:</b>								<b>46.5</b>		<b>361</b>	
<b>Grand Total:</b>								<b>46.5</b>		<b>361</b>	