

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	24-JUN-24	B	S04	13	4616	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	2	G083
		B	S04	1	4661	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	2	4662	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	3	4663	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	4	4664	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	5	4665	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	6	4666	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	7	4667	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	8	4668	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	9	4669	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	10	4670	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	11	4671	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S04	12	4672	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	1	G083
			<b>Machine Total:</b>					<b>12</b>		<b>91</b>	
	24-JUN-24	B	S06	13	4630	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	1	4674	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	2	4675	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	3	4676	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	4	4677	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	5	4678	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	6	4679	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	7	4680	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	8	4681	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	10	4682	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	9	4682	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	11	4683	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S06	12	4684	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	4	G083
			<b>Machine Total:</b>					<b>12</b>		<b>99</b>	
	24-JUN-24	B	S07	1	4687	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	2	4688	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	3	4689	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	4	4690	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	5	4691	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	6	4692	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	7	4693	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	8	4694	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	9	4695	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	10	4696	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S07	11	4697	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S07	12	4698	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S07	13	4699	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	4	G083
			<b>Machine Total:</b>					<b>12.5</b>		<b>91</b>	
	24-JUN-24	B	S08	12	4589	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	2	G083
		B	S08	13	4644	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	4	G083

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	24-JUN-24	B	S08	1	4700	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	2	4701	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	3	4702	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	4	4703	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	5	4704	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	6	4705	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	7	4706	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	8	4707	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	9	4708	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	10	4709	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	8	G083
		B	S08	11	4710	386	R	.5	I052 S BEAM 325-399 L/L 100 YDS.	5	G083
<b>Machine Total:</b>								<b>11.5</b>		<b>91</b>	
<b>Shift Total:</b>								<b>48</b>		<b>372</b>	
<b>Day Total:</b>								<b>48</b>		<b>372</b>	
<b>Type Total:</b>								<b>48</b>		<b>372</b>	
<b>Grand Total:</b>								<b>48</b>		<b>372</b>	