

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	02-JUL-24	B	S02	1	4188	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	2	4189	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	3	4190	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	4	4191	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	5	4192	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	6	4193	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	7	4194	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	8	4195	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	9	4196	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	10	4197	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	11	4198	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S02	12	4199	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
<b>Machine Total:</b>								<b>12</b>	<b>84</b>		
	02-JUL-24	B	S04	1	4200	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	2	4201	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	3	4202	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	4	4203	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	5	4204	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	6	4205	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	7	4206	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	8	4207	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	9	4208	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	10	4209	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	11	4210	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S04	12	4211	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
<b>Machine Total:</b>								<b>12</b>	<b>84</b>		
	02-JUL-24	B	S06	1	4212	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	2	4213	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	3	4214	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	4	4215	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	5	4216	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	6	4217	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	7	4218	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	8	4219	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	9	4220	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	10	4221	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	11	4222	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S06	12	4223	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
<b>Machine Total:</b>								<b>12</b>	<b>84</b>		
	02-JUL-24	B	S07	1	4224	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	2	4225	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	3	4226	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	4	4227	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	5	4228	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083

MURLIDHAR RATANLAL EXPORTS LIMITED  
 UNIT: HASTINGS JUTE MILL

Print Date : 03-JUL-24 09:13 AM

TYPE	DATE	SHIFT	MACHINE NO	SRL.	BILLET NO	ENDS	SELVEGE	BEAM	BEAMING QUALITY	PRODUCTION	WEAVING QUALITY
S	02-JUL-24	B	S07	6	4229	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	7	4230	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	8	4231	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	9	4232	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	10	4233	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
		B	S07	11	4234	386	R	1	I052 S BEAM 325-399 L/L 100 YDS.	7	G083
<b>Machine Total:</b>								<b>11</b>		<b>77</b>	
<b>Shift Total:</b>								<b>47</b>		<b>329</b>	
<b>Day Total:</b>								<b>47</b>		<b>329</b>	
<b>Type Total:</b>								<b>47</b>		<b>329</b>	
<b>Grand Total:</b>								<b>47</b>		<b>329</b>	