

MURLIDHAR RATANLAL EXPORTS LIMITED

UNIT: GONDALPARA JUTE MILL

Qualitywise Efficiency Report For 11-JUN-24 to 20-JUN-24

HESSIAN SKG.

27-JUN-24 03:40 PM

Page 1 of 2

Wastage : 0.0

| Shift | T/Hrs | L/Hrs | W/Hrs |
|-------|-------|--------|-------|
| A | 64.00 | - 0.00 | 64.00 |
| B | 64.00 | - 0.00 | 64.00 |
| C | 60.00 | - 0.00 | 60.00 |

188

| Qlty Code | Quality Port | Shot | Specifications Width | Description | R.S. | Laid Lngth | Fin. Lngth | No of Cuts | Total Yds/mtr | Gms/ Yds | Wt in Kg | Total Yds/mtr | Eff% | Total Loom Hour | No of Looms | Kg/ Loom/Hour |
|-------------------|--------------|------|----------------------|-----------------------------|------|------------|------------|------------|---------------|----------|----------|---------------|-------|-----------------|-------------|---------------|
| 33 | 5 | 7 | 22.5 | 5 X 7 - 22.5" / 9.14 OZS | 32" | 130 | | 1104 | 131376 | 283 | 37227 | 409138.9 | 81.88 | 4386.69 | 560 | 67.89 |
| | 5 | 7 | 22.5 | 5 X 7 - 22.5" / 9.14 OZS | 37" | 130 | | 3083 | 366877 | 283 | 103959 | 1144101.5 | 81.76 | 12643.00 | 1614 | 65.78 |
| Quality Total --> | | | | | | | | 4187 | 498253 | | 141186 | 1553240.4 | 81.82 | 17029.69 | 2174 | 8.29 |
| 33 --> | | | | | | | | 4187 | 498253 | | 141186 | 1553240.4 | 81.82 | 17029.69 | 2174 | 8.29 |
| Qlty Code | Quality Port | Shot | Specifications Width | Description | R.S. | Laid Lngth | Fin. Lngth | No of Cuts | Total Yds/mtr | Gms/ Yds | Wt in Kg | Total Yds/mtr | Eff% | Total Loom Hour | No of Looms | Kg/ Loom/Hour |
| 33 | 5 | 7 | 22.5 | 5 X 7 - 22.5" / 9.14 OZS | 37" | 130 | | 2386 | 357900 | 283 | 102073 | 1177318.0 | 77.52 | 8836.00 | 1128 | 92.42 |
| 34 --> | | | | | | | | 2386 | 357900 | | 102073 | 1177318.0 | 77.52 | 8836.00 | 1128 | 11.55 |
| Qlty Code | Quality Port | Shot | Specifications Width | Description | R.S. | Laid Lngth | Fin. Lngth | No of Cuts | Total Yds/mtr | Gms/ Yds | Wt in Kg | Total Yds/mtr | Eff% | Total Loom Hour | No of Looms | Kg/ Loom/Hour |
| 10 | 5 | 7 | 32 | 5 X 7 - 32 / 12.57 OZS | 52" | 118 | | 63 | 7182 | 390 | 2798 | 27032.4 | 67.75 | 329.00 | 42 | 68.04 |
| 28 | 5 | 7 | 42 | 5 X 7 - 42" / 16.50 OZS | 52" | 118 | | 49 | 5586 | 512 | 2857 | 27032.4 | 52.69 | 329.00 | 42 | 69.47 |
| --> | | | | | | | | 112 | 12768 | | 5655 | 54064.8 | 60.22 | 658.00 | 84 | 8.59 |
| Grand Total : | | | | | | | | 6685 | 868921 | | 248914 | 2784623.2 | 72.32 | 26523.69 | 3386 | 9.38 |

Overseer

Weaving I/C

Asst. Manager.(Fact.)

M.Manager

P.Manager

C.M. Manager

MURLIDHAR RATANLAL EXPORTS LIMITED

UNIT: GONDALPARA JUTE MILL

Qualitywise Efficiency Report For 11-JUN-24 to 20-JUN-24

HESSIAN WVG.

27-JUN-24 03:40 PM

Page 2 of 2

Wastage : 0.0

| Shift | T/Hrs | L/Hrs | W/Hrs |
|-------|-------|--------|-------|
| A | 56.00 | - 0.00 | 56.00 |
| B | 56.00 | - 0.00 | 56.00 |
| C | 52.50 | - 0.00 | 52.50 |

164.5

| Qlty Code | Quality Port | Shot | Specifications Width | Description | R.S. | Laid Lngth | Fin. Lngth | No of Cuts | Total Yds/mtr | Gms/ Yds | Wt in Kg | Total Yds/mtr | Eff% | Total Loom Hour | No of Looms | Kg/ Loom/ Hour |
|-----------------------------|--------------|------|----------------------|--------------------------------|------|------------|------------|-------------|---------------|----------|--------------|-----------------|---------------|-----------------|-------------|----------------|
| 101 | 11 | 12 | 48 | 11 X 12 -48" / 12 OZS | 54" | 160 | | 220 | 30800 | 372 | 11458 | 118816.7 | 52.68 | 3141.17 | 401 | 29.18 |
| 125 | 9 | 8 | 48 | 9 X 8 - 48" / 8.40 OZS | 54" | 109 | | 10 | 1400 | 260 | 365 | 4889.0 | 58.42 | 86.17 | 11 | 33.89 |
| 392 | 11 | 11 | 54 | 11 X 11 - 54" / 12.60 OZS. | 56" | 160 | | 2 | 280 | 391 | 109 | 1275.2 | 44.79 | 31.33 | 4 | 27.83 |
| | 11 | 11 | 54 | 11 X 11 - 54" / 12.60 OZS. | 66" | 160 | | 25 | 3500 | 391 | 1367 | 14833.5 | 47.6 | 391.66 | 50 | 27.92 |
| Quality Total --> | | | | | | | | 27 | 3780 | | 1476 | 16108.7 | 46.195 | 422.99 | 54 | 3.49 |
| 393 | 9 | 7 | 36 | 9 X 7 - 36" / 5.85 OZS | 52" | 160 | | 264 | 36960 | 181 | 6703 | 121002.1 | 61.91 | 1840.84 | 235 | 29.13 |
| 42 | 11 | 12 | 45 | 11 X 12 - 45" / 11.25 OZS | 52" | 160 | | 93 | 13020 | 349 | 4541 | 41449.7 | 63.73 | 1081.00 | 138 | 33.61 |
| 66 --> | | | | | | | | 614 | 85960 | | 24543 | 302266.2 | 54.86 | 6572.17 | 839 | 3.73 |
| Qlty Code | Quality Port | Shot | Specifications Width | Description | R.S. | Laid Lngth | Fin. Lngth | No of Cuts | Total Yds/mtr | Gms/ Yds | Wt in Kg | Total Yds/mtr | Eff% | Total Loom Hour | No of Looms | Kg/ Loom/ Hour |
| 279 | 9 | 7 | 60 | 60" - 6.5 OZS / 40" X 7 | 190" | | | 41 | 8423 | 198.4 | 2547 | 12888.7 | 66.83 | 289.83 | 37 | 70.30 |
| 293 | 11 | 10 | 59 | 59.0" - 8.5 OZS / 40" X 10.00 | 190" | | | 158 | 32504 | 259.4 | 12636 | 58034.0 | 56.61 | 1864.33 | 238 | 54.22 |
| 297 | 9 | 8 | 50 | 50.0" - 7.00 OZS / 40" X 9.00 | 190" | | | 174 | 35547 | 213.6 | 9643 | 53644.9 | 67.62 | 1378.66 | 176 | 55.96 |
| 307 | 9 | 7 | 50 | 50.0" - 6.5 OZS / 40" X 9.00 | 190" | | | 29 | 5915 | 198.4 | 1490 | 8708.6 | 69.37 | 195.83 | 25 | 60.87 |
| 321 | 11 | 11 | 54 | 54.0" - 9.34 OZS / 40" X 11.00 | 190" | | | 128 | 26160 | 285 | 10226 | 51871.5 | 51.51 | 1833.00 | 234 | 44.63 |
| 395 | 9 | 8 | 60 | 60" - 7.00 OZS / 40" X 9 | 190" | | | 133 | 26856 | 213.6 | 8742 | 41757.7 | 65.4 | 1073.17 | 137 | 65.17 |
| 397 | 9 | 9 | 51 | 51" - 7.5 OZS / 40" X 9 | 190" | | | 82 | 17052 | 228.9 | 5056 | 24655.0 | 70.44 | 712.82 | 91 | 56.74 |
| 67 --> | | | | | | | | 745 | 152457 | | 50340 | 251560.4 | 63.97 | 7347.64 | 938 | 6.85 |
| Grand Total : | | | | | | | | 1359 | 238417 | | 74883 | 553826.6 | 59.76 | 13919.81 | 1777 | 5.38 |

Overseer

Weaving I/C

Asst. Manager.(Fact.)

M.Manager

P.Manager

C.M. Manager

Dy.G.M

G.Manager